



1. Slot chosen Flexi Neck Tool onto the top pole (orange band at top)

2. Slot your chosen end tool into the open end of the Flexi Neck

FLEXI-NECK TOOLS



END TOOLS



3. Slot chosen number of poles together to reach desired height & attach cuff with non-tapered end to the bottom pole



4. Attach one end of the Flexi-Hose into the tapered end of the cuff

5. Slot the open end of Flexi-Hose into vacuum port

REF: UK15400004



EXTERNAL HIGH REACH
4 POLE PACKAGE



REF: UK154000005



EXTERNAL HIGH REACH
6 POLE PACKAGE



REF: UK15400006



EXTERNAL HIGH REACH
8 POLE PACKAGE

